



State of Utah

DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF AIR QUALITY



10903AIR

SSIU IC

Michael O. Leavitt
Governor

Dianne R. Nielson, Ph.D.
Executive Director

Ursula K. Trueman
Acting Director

150 North 1950 West
P.O. Box 144820
Salt Lake City, Utah 84114-4820
(801) 536-4000 Voice
(801) 536-4099 Fax
(801) 536-4414 T.D.D.

November 18, 1996

DAQC-1956-96

Dale Hansen
Thatcher Company
P.O. Box 27407
1905 West Fortune Road
Salt Lake City, Utah 84127

add this
info to
SV table

Dear Mr. Hansen:

Re: Thatcher Company - Protocol Review and Test Date Confirmation - Thatcher Company,
Impinjet SO2 Scrubber - Salt Lake County

A review of the emissions testing protocol received October 17, 1996, and additional information received November 12, 1996, has been conducted and the protocol has been accepted. The test date that has been agreed upon is November 19, 1996.

Acceptance of the protocol, however, does not relieve the owner/operator and testing contractor from strict adherence to all applicable EPA Methods, Division Policies, Utah Air Conservation Rules (UACR), and methods approved by the Executive Secretary. Any deviation from EPA Methods, Division Policies, UACR, and methods approved by the Executive Secretary, must be addressed separately and express written consent given prior to the commencement of testing.

If you have any questions, please contact me at (801) 536-4028.

Sincerely,

Anthony DeArcos, Environmental Scientist
Division of Air Quality

AD:tj

cc: Salt Lake City/County Health Department
EPA Region VIII, Lee Hanley

